# Electric Motor Maintenance and Troubleshooting

Second Edition

Augie Hand



New York Chicago San Francisco Lisbon London Madrid Mexico City Milan New Delhi San Juan Seoul Singapore Sydney Toronto

# Contents

Troubleshooting Single-Phase Motorsxvi
Troubleshooting Three-Phase Motors xix
Troubleshooting the DC Machinexx
Introduction xxii
CHAPTER 1 The DC Machine
Basic Electricity as It Applies to Motors
Volts
Resistance
Amperes
Additional Information on Copper Wire
Ohm's Law
Watt
Magnets and the Magnetic Circuits
The Bar Magnet6
The Electromagnet
The Magnetic Pole6
Ampere Turns
The Magnetic Circuit
Magnetic Saturation
Magnetic Balance
Neutral Position in the Stator
Circuits of the DC Machine
Rules for Generating Direct Current
The Shunt Generator
The Armature and Interpoles
The Shunt Field

## **vi** Contents

Operation of the Self-Excited Shunt Generator	117
Shunt Generator Control	18
The Series Generator	19
Operation of the Self-Excited Series Generator	19
The Compound Generator	20
The Armature and Interpoles	20
The Series Field	21
The Shunt Field	21
Operation of the Self-Excited Compound Generator	21
Compound Generator Control	22
The Cumulative Compound Connection (Generator)	23
The Differential Compound Connection (Generator)	
Series Field Connections for a Motor and a Generator	24
Special-Purpose Machine Connections	
The DC Arc Welder	
Operation of the DC Welder Generator	
Operation of the Welder's Reactor	
Interpoles	
Operation of Interpoles	
The Compensating Winding	
Operation of a DC Motor	
One Armature Conductor in a Generator as It Passes Two Poles	
One Armature Conductor in a Motor as It Passes Two Poles	
Counter-voltage	
Counter-voltage Compared to Charging a Battery	
Counter-voltage in a Motor Armature	
Base Speed	
Below Base Speed	
Above Base Speed	
Torque of the DC Motor	
The Shunt Motor	
The Armature and Interpoles	
The Shunt Field.	
Operation of the Shunt DC Motor	
The Permanent Magnet DC Motor	
Operation of the Permanent Magnet Motor	
Restoring Magnetism	
The Series Motor	
Operation of the Series Motor	41

	Contents	vii
The Compound DC Motor		42
The Armature and Interpoles		42
The Shunt Field		42
The Series Field		43
Operation of the Compound Motor Connected		
Cumulative Compound		43
The Stabilized Shunt Motor		43
Speed Control for a Compound DC Motor		44
Armature Control for Starting and for Below Base Speed	l	44
Shunt Field Control for Starting and for Above Base Spe-	ed	44
The Differential Connection (Motor)		45
Armature Components		46
Commutator		47
Commutator Film		48
Armature Windings		49
Equalizer Shunts		50
Laminated Iron		50
Chapter 1 Review		51
CHAPTER 2 Troubleshooting and Testing the DC Machine		. 57
Armature Problems		
Burned Commutator Bars		
Dirty Commutator		
Dead Spots from an Open Armature Coil		
Open Equalizer		
Stalled Motor		
Control and Load Problems		
Brushes		
Brush Problems		
Conduction Zone		
Spiral Groove		
Multiple Brushes		
Brush Box and Commutator Spacing		
Distance Between Brushes		
Brush Holder Alignment		
Spring Tension		
Brush Shunts		
Side Wear		
Uneven Commutator Segments		65

### viii Contents

Brush Dusting	65
Low Load Current	65
Silicone Vapor and Adverse Ambient Conditions	66
Seating Brushes	67
Neutral Location in the Stator and Armature	68
Setting Neutral in a Motor	68
Black Band Adjustment	69
Setting Neutral in a Generator	69
Restoring Residual Magnetism After Setting Neutral	69
Overheated Motor	70
Field Testing the DC Machine	70
Field Testing the Armature	70
Field Testing for Grounds in the Armature Circuit	
with an Ohmmeter	71
Field Testing the Shunt Field	71
Field Testing the Series Field	75
Locating Problems in the DC Machine	78
Locating Problems in the Armature	79
Locating a Grounded Interpole with AC and a Clamp-on Ammeter	80
Locating a Shorted Interpole Using the AC Voltage Drop Test	82
Locating a Shorted Interpole Using the Smoke Test	83
Locating Problems in the Shunt Field	83
The Comparison Test	83
Needle Probes	83
Variations in the Shunt Field Circuitry	84
Drawing Simple Schematics of a Shunt Field	84
Drawing a Diagram of a Two-Circuit Shunt Field	84
Drawing a Diagram of a Two-Circuit, Two-Coils-per-Pole	
Shunt Field	85
Ground to the Frame Symptom	87
Shorted Turns in the Shunt Field Symptoms	89
Shunt Field with an Open Circuit	
Shunt Field Shorted to the Series Field Symptoms	93
Locating Problems in the Series Field	94
Ground to Frame Symptoms	95
Shorted Turns in the Series Field Symptoms	
Locating an Open Circuit in Series Field	98
Identifying Leads of a Compound DC Motor with an Ohmmeter	99
Chapter 2 Review	100

	Contents	ix
CHAPTER 3 AC Electric Motor Theory		105
AC Terminology		
Generating Alternating Current		
Cycles and Hertz		
Electrical Degrees and Time		108
Electrical Degrees and Mechanical Degrees		111
Degrees and Location		111
Two-Phase Power		
Two-Phase Rotating Magnetic Field		
Revolutions per Minute, Poles, and Hertz		
The Single-Phase Alternator		
Current, Ampere, Power, and Reactive Terms		
Inductive Reactance		
Impedance		118
Inductive Reactance and Counter-voltage		118
Power Factor		118
Unity Power Factor		118
Magnetizing Amperes and Lagging Power Factor		119
Power Factor in Motors		
Low Power Factor Concerns		121
Inductive Reactance and Hertz Change		122
Formula for 50-Hz to 60-Hz Power Change		122
Impedance in a Three-Phase Winding		122
Capacitance and Capacitive Reactance		
Capacitor Function		123
Capacitor Value		124
Capacitors for Single-Phase Motors		125
Oil-Filled Capacitor		
Oil-Filled Capacitor in Single-Phase Motors		
Oil-Filled Capacitor Components		126
Oil-Filled Capacitor Connection in a Two-Value		
Capacitor Single-Phase Motor		
Mounting the Oil-Filled Capacitor		
Electrolytic Capacitors		
Electrolytic Capacitor Function in the Capacitor-Start Mo		
Electrolytic Capacitor Components		
Electrolytic Capacitor and Start-Winding Connections		
Parallel Electrolytic Capacitor Connection		
Series Electrolytic Capacitor Connection		
Testing the Electrolytic Capacitor		133

### **x** Contents

	Capacitor lest Formula
	Determining the Right Size Capacitor135
	Operation of the Single-Phase Capacitor-Start Motor
	Transformer Theory
	Transformer Components138
	Transformer Function139
	Transformer Rating139
	Solder Gun Transformer
	The Squirrel Cage Rotor
	Current Flow in Stator Coils
	Function of the Squirrel Cage Rotor
	Rotor Hertz and Amperes
	Slip, Hertz, and Motor Speed
	Synchronous Speed and Zero Torque
	Rotor Bar Stress
	Broken Rotor Bars
	Cracked End Rings
	Misaligned Rotor Iron
	Chapter 3 Review149
CHAF	TER 4 The Single-Phase Motor
CHAF	
CHAF	Shaded-Pole Motor155
CHAF	Shaded-Pole Motor
CHAF	Shaded-Pole Motor155
CHAF	Shaded-Pole Motor
CHAF	Shaded-Pole Motor
CHAF	Shaded-Pole Motor
CHAF	Shaded-Pole Motor158Multispeed Shaded-Pole Motor156Troubleshooting the Shaded-Pole Motor156Split-Phase Motor157Components of the Split-Phase Motor157Operation of the Split-Phase Motor158
CHAF	Shaded-Pole Motor158Multispeed Shaded-Pole Motor156Troubleshooting the Shaded-Pole Motor156Split-Phase Motor157Components of the Split-Phase Motor157Operation of the Split-Phase Motor158Troubleshooting the Split-Phase Motor158Capacitor Motors158
CHAF	Shaded-Pole Motor155Multispeed Shaded-Pole Motor156Troubleshooting the Shaded-Pole Motor156Split-Phase Motor157Components of the Split-Phase Motor157Operation of the Split-Phase Motor158Troubleshooting the Split-Phase Motor158
CHAF	Shaded-Pole Motor158Multispeed Shaded-Pole Motor156Troubleshooting the Shaded-Pole Motor156Split-Phase Motor157Components of the Split-Phase Motor157Operation of the Split-Phase Motor158Troubleshooting the Split-Phase Motor158Capacitor Motors158The Capacitor-Run Motor158The Capacitor-Start Motor161
CHAF	Shaded-Pole Motor158Multispeed Shaded-Pole Motor156Troubleshooting the Shaded-Pole Motor156Split-Phase Motor157Components of the Split-Phase Motor157Operation of the Split-Phase Motor158Troubleshooting the Split-Phase Motor158Capacitor Motors158The Capacitor-Run Motor158
CHAF	Shaded-Pole Motor

	Contents	хi
Alternative Start-Winding Switches		186
Potential Relay Start Switch		186
Electronic Start Switch		
Time-Delay Electronic Start Switch		
Heat-Activated Start Switch		
Current Relay Start Switch		193
Chapter 4 Review		
CHAPTER 5 The Three-Phase Induction Motor		201
Components of the Three-Phase Motor		
Rotor and Fan		
Stator Core		
Shell and Frame		
End Brackets		
Bearings		
Operation of the Three-Phase Motor		
The Rotating Magnetic Field in a Three-Phase Motor		
Single-Phase Condition		
Amperes and Rotor Bar Design		
Phase Angle		
Small Rotor Bars		
Large Rotor Bars		212
Code Letter		
Torque and Speed		213
Design Letter		214
Introduction to Three-Phase Motor Types		
The Nine-Lead Induction Motor		217
Nine-Lead Wye Connection		219
Nine-Lead Multiple-Wye Connection with T10		220
Thermal Protector for the Nine-Lead		
Wye-Connected Motor		222
Nine-Lead Delta Connection		223
Multiple-Delta Connection		224
Twelve-Lead Connection		224
Multispeed Motors		. 227
Single-Winding Two-Speed Motors		. 227
Constant-Horsepower Motor		
Constant-Torque Motor		
Variable-Torque Motor	. , ,	. 229

### **xii** Contents

	Multispeed Multiwinding Motor	230
	Two-Speed Two-Winding Motor	231
	Multimode Nine-Lead Three-Phase Motors	231
	Comparing Multimode Motors to Standard Motors	232
	Triple-Mode, Nine-Lead Three-Phase Motor	233
	Identifying the Triple-Mode, Nine-Lead Three-Phase Motor	234
	Quadruple-Mode, Nine-Lead Three-Phase Motor	235
	Identifying the Quadruple-Mode, Nine-Lead	
	Three-Phase Motor	
	Synchronous Motor	
	Components of the Synchronous Motor	239
	Operation of the Synchronous Motor	240
	The Synchronous Motor Control	
	Power Factor Correction with a Synchronous Motor	243
	The Brushless Synchronous Motor	
	Three-Phase Alternator	244
	Wound Rotor Motor	
	Components of the Wound Rotor Motor	
	Operation of the Wound Rotor Motor	
	Liquid Used for Speed Control	
	Reversing the Wound Rotor Motor	
	Wound Rotor Motor Used as a Variable-Voltage Transformer	
	Wound Rotor Motor Used as a Hertz Changer	
	The Brushless DC Motor	
	Components of Brushless DC Motors	
	Operation of the Brushless DC Motor	
	Three-Phase Servo Motors	
	Identifying the Three-Phase Induction Motor	
	Nine-Lead Dual-Voltage Motors	
	Three-Lead Motors	
	Six-Lead Motors	
	Twelve-Lead Single-Speed Motors	
	Dual-Voltage Multispeed Motors	
	European Connections	
	Chapter 5 Review	269
ΉΑ	APTER 6 Troubleshooting Three-Phase Motors	275
	The Dual-Voltage Nine-Lead Motor's Internal Connections	
	Understanding the Nine-Lead Wye Connection	
	oridorstanding the mine-bead wye confidential	4/3

	Contents	xiii
Understanding the Nine-Lead Delta Connection		. 278
Smaller Wire Size with Delta and Multicircuit Winding.		. 281
Identifying Unmarked Leads in a Nine-Lead Three-Phase Mo	otor	. 285
Identifying Unmarked Leads in a Wye Connection		. 285
Identifying Unmarked Leads in a Delta Connection		
Theory of Unmarked Lead Test		
Typical Winding Problems		
Shorted Turns		
Ground		
Phase-to-Phase Short		
Open Winding		. 298
Burned Windings from Operating on Single Phase		
Submerged Motor		
Assorted Rotor Problems		
When Motors Overheat		.304
Line-Caused Overheating		.304
Operator-Caused Overheating		.309
Control-Caused Overheating		. 311
Motor Fault Overheating		. 312
Location-Caused Overheating		. 316
Maintenance-Caused Overheating		. 316
Chapter 6 Review		. 317
CHAPTER 7 Troubleshooting Less Common Motors		321
Troubleshooting Logic Using Voltage Rules		
Troubleshooting Less Common Motors		
Troubleshooting Identified Motors		
Troubleshooting the Synchronous Motor		
The DC Exciter Field and Discharge Resistor		
The Amortisseur Winding		
Stator Winding		
Troubleshooting the Two-Speed One-Winding Motor		
Troubleshooting Multispeed Multiwinding Motors		
Circulating Current in Multiwinding Multispeed Motor		
Rotor Problems in the Multispeed Motor		
Testing Motors in Place		
Test Instruments for Testing in Place		
Core and Rotor Damage		
Troubleshooting the Nine-Lead Motor (Wye or Delta) in		

### **xiv** Contents

Visual Check of the Nine-Lead Motor (Wye or Delta)	4
Testing from Control (Wye or Delta)	
Starting the Motor After the Comparison Test from Control 339	9
Line/Lead Interchange Test for Uneven Amperes	
Recording Motor Faults339	9
Locating Motor Faults	0
Test Equipment for Locating Motor Faults	0
Locating Shorted Turns in a Wye-Connected Nine-Lead Motor 34	1
Locating Voltage Spike Damage in a Wye-Connected	
Nine-Lead Motor	2
Locating Shorted Turns in a Delta-Connected Nine-Lead Motor 34	4
Megohmmeter Test for Ground	6
Bearing Maintenance	6
Motor Storage Concerns	7
Bearing Failure Causes348	8
Lubrication Schedule and Bearing Life	0
Grease Types	1
Changing Grease Types	
Lubrication Procedure352	
Alternate Lubrication Methods353	3
Gearbox Lubrication	3
Shielded Bearings	4
Sealed Bearings354	
Labyrinth Seal354	
Bearing Removal	
Bearing Installation358	
Identifying Bearing Breakdown Causes	
Specialized Bearing Tools	
Sleeve Bearings	
Chapter 7 Review	3
CHAPTER 8 Test Instruments and Services	,
Instruments for Initial Testing	
Voltmeter	
Clamp-on Ammeter	
Ohmmeter371 Microhmmeter372	
Tachometer	
Megohmmeter374	Ŧ

	Contents	χV
Infrared Gun		.376
Stethoscope		.377
Instruments for In-depth Testing and Scheduled Maintenance		.377
Surge Tester	. ,	.378
Rotor Test		.380
Polarization Index Test with a Megohmmeter		. 381
Step Voltage Test		. 383
High-Potential Test		. 385
Power Quality Test Instruments		. 386
Vibration Sensors		.388
Laser Alignment		. 389
Particle Analysis		. 390
Chapter 8 Review		. 391
Index		393